ABB i-bus [®] KNX	Firmware Information
Product:	Telephone Gateway, analogue, MDRC
Туре:	TG/S 3.2
Current firmware version:	0.1.41
Firmware Information	to: 0.1.41 from: 09/2010
1. <u>Correction:</u>	When calling mobile phones in a message loop it could rarely happen that the message loop was ended unintentionally. This error was corrected with version 0.1.41.
======================================	to: 0.1.40 from: 05/2010
1. <u>Correction:</u>	After the phisical address of the device has been changed, the new address was displayed in the browser and in the IP Firmware Tool after the device has been restarted. Now the new physical address will be displayed without the restart.
======================================	to: 0.1.39 from: 04/2010
1. <u>Corrections:</u>	After bus voltage recovery also the value of inactive objects was read via the bus. From this firmware version the values will not be read anymore. The operation of DPT 1.008 (shutter control) the UP and DOWN command were interchanged. This is now corrected.
======================================	to: 0.1.37 from: 03/2010

^{1. &}lt;u>Error Correction (important):</u>

ABB i-bus [®] KNX	Firmware Information
	In case of hang up of a user in a sub menu (without pressing the button "#") it could have happened, that the Telephone Gateway did not hang up. Hence the TG could not be called by the user, until the TG transmitted a
	message itself. The error occurred if the browser parameter <i>Time between two busy signals</i> had the value <i>0.5 seconds</i> (standard setting).
	The error is solved from version 0.1.37.
2. <u>Further Corrections:</u>	The following minor errors were solved:
	The fill characters in the password input were not displayed correctly on the Internet Explorer 7 and 8.
	The speech messages 10a to 10d could not be overwritten by the customer.
	On the reception of a text string object value "00 00 00 00 00 00 00 00 00 00 00 00 00
	When resetting the device to the default settings, it could happen, that some user defined speech messages were not reset correctly.
	to: 0.1.33 from: 06/2009
1. <u>PDA view:</u>	From this version the device is able to display browser pages fitting on the standard resolution for PDA's or mobile phones (see description in the product manual).
2. <u>Increased speed:</u>	The creation of the HTML pages in the browser view was accelerated. This led to a significant improvement of the browser based operation and configuration.
Firmware Information	to: 0.1.28 from: 06/2008
1. <u>First version</u>	